

- 1. Scope
- 2. Process description
- 3. Design and operating principle of vibration welding machines
- 3.1. Machine types
- 3.2. Requirements for vibration welding machines
- 3.3. Individual components
- 3.3.1. Drive systems

4. Machine parameters and process variables

- 4.1. Frequency f (Hz), amplitude a (mm)
- 4.2. Welding pressure p_s (N/mm²)
- 4.3. Welding time $t_s(s)$
- 4.4. Welding penetration s_s (mm) and holding penetration s_H (mm)
- 4.5. Holding pressure p_{H} (N/mm²) and holding time t_{H} (s)
- 4.6. Temperature in the joining zone

5. Welding behaviour of plastics

- 5.1. General
- 5.2. Welding of plastics of the same sort and same type
- 5.3. Welding of plastics of the same sort but of d teren
- 5.4. Welding of different sorts of plastic
- 5.5. Joining of plastics with dissimilar materials
- 5.6. Admixtures: filling and reinforcing materials
- 5.7. Additives
- 5.8. Water absorption
- 5.9. Influence of recycled materials

6. Quality requirements for parts to be joint

7. Design of the moulded par s

- 7.1. General requirements for the could d part
- 7.2. Weld seam design
- 7.3. Examples of joining zo geometries
- 7.3.1. Simple butt weld
- 7.3.2. Butt weld concrele for the side
- 7.3.3. Butt weld conceals on both sides
- 7.4. Measures for r hable a physicism of the amplitude
- 7.5. Centring aids

8. Holding tool.

9. Weld Loca fo mation

- 9.1. Abrasion and uzzing
- 9.2. Combined vibration welding with pre-heating to minimise abrasion and fuzzing.

hed

10. Juain, assurance measures

References

11

- Regulations
- Bibliography